WMWI - Metro Landfill, AUDIT PHOTOS

PROJECT NO. 1036.10056

Equipment issues prevented the record document from today's audit.

The most important observation for the day was that cover is well improved for both daily and intermediate placement

Future cell excavation



AUDIT PHOTOS - 1



Phase 3 receiving waste



Phases 2 & 3 viewed from the South

JSA ENVIRONMENTAL



Working face at North end of Phase, being covered



Phase 1 & portion of 2 with top soil cover to grow vegetation, reduce erosion and dust



East slope of Phase 1 top soil cover for vegetation growth



Previous lift across Phase 3 and future cell location

JSA ENVIRONMENTAL



Working face at North end of Phase 3, waste mass nearly cresting



Working face at North end of Phase 3, overlaying on to Phase 2

WMWI - METRO LANDFILL Action Items Checklist City of Franklin Audit									
Opened:							Updated: 01/11/2024		
Item Number	DATE	Condition Description	Permit or Contract Reference	Reported to	Initial Schedule for Completion	Actual Completion Date	Elapsed Time (Days)	Notes	
1									
	I	1		1	I	1		11	