
litor on site at: TE: <u>Nove</u> Overcast with low clou	Open mber 5, 202	4	Close			
	mber 5, 202	4	<u> </u>			
			Comple	eted 🗵		
Overcast with low clou			_ 0 0p. 0		NW 10	to 15 mph
	ıds			WIN	D N S	s e w
ium 🔒	- °E	Minimum				
ium4	9	—	33	<u>3 °F</u> B.I	P. 30.12	
	-		No.	DESCRIPTION	Rented	Contracted
Compactor		-				
Dozer		-				
Excavator						
Haul Truck						
Water Truck						
ENT BONEYARD						
CRIPTION	Broken	Maintenance	No.	DESCRIPTION	Broken	Maintenand
Compactor		Х				
e Size and Locatio)n:					
)h with tipper pointed	South Ma	ding food poorly	finished w	ith full travel cores		North to Sour
b, with tipper pointed	300tin. WOI	king lace hearly	IIIISHEU W			
	PMENT USED IN LA CRIPTION Trailer Tipper Compactor Dozer Excavator Haul Truck Water Truck ENT BONEYARD CRIPTION Compactor	PMENT USED IN LANDFILL OF CRIPTION Rented Trailer Tipper Compactor Dozer Excavator Haul Truck Water Truck Water Truck ENT BONEYARD CRIPTION Broken Compactor I Size and Location:	PMENT USED IN LANDFILL OPERATIONS CRIPTION Rented Contracted Trailer Tipper Compactor Dozer Excavator Haul Truck Water Truck Water Truck ENT BONEYARD CRIPTION Broken Maintenance Compactor X Size and Location:	PMENT USED IN LANDFILL OPERATIONS CRIPTION Rented Contracted No. Trailer Tipper	MENT USED IN LANDFILL OPERATIONS CRIPTION Rented Contracted No. DESCRIPTION Trailer Tipper	PMENT USED IN LANDFILL OPERATIONS CRIPTION Rented Contracted No. DESCRIPTION Rented Trailer Tipper


Page 1 of 6

	Cover Material:										
	Soils, MRF Fines, and Tarp										
В.	Leachate Management: Discharge to MMSD Discharge Volume: 30,000 gpd Leachate Head Levels: All within statutes										
C.	Gas Monitoring and Management: Check appropriate box. Flares in Operation: YES NO # 1 Turbines in Operation: YES NO # 1 Engines in Operation: YES NO # 3 Shutdowns Since Last Audit: # 11/17 thru 19/2024 Destructed Volume: # 3,200 cfm										
	Comments:										
	Plant down due to valve issues earlier in the week. Turbine plant manager splitting time with Orchard Ridge New gas header being added to North 60										
D.	 Surface Water Management: Storm Events Since Last Audit: # 3 Est. Volume ~1" EFFECTS: Note condition of perimeter road, erosion control structures, erosion damage and possible storm water/waste contact locations: 										
	Rain and snow events earlier this week. Site still appears quite dry										
	Basins have plenty of freeboard and erosion unchanged										
E.	Odor Control: Odors Present: Onsite Offsite Notes on odor monitoring page Comments:										
	No odors										
F.	Liquid Loads Received:										
	Typical loading 10% less than MSW receipts Page 2 of 6										

i.	Litter Control:									_	
	Litter Present O	nsite:	YES		NO						
	Litter Present O	ffsite:	YES		NO						
	Laborers Active	9:	YES		NO		#4				
	Comments:										
	Laborers have recovered litter from beginning of month and today are installing additional litter fence										
H. Vehicle Impacts: Locations of excessive mud/dust, condition of access and public roads and control meas										ess and public roads and control measures	
	taken, instances c										
	US 45 dusty, but c	lear of deb	oris. Si	te ro	ads di	istv k	out cle	ar as well			
	Inspection of in	comina	Wast	۵.							
	Scale Camera Op	0	YES		NO			#			
	Equipment Opera		YES		NO	믐		#	7	-	
	Spotter:		YES		NO			#	,	-	
	· · · · · · · · · · · · · · · · · · ·					11/21	/2024			-	
	Random Load Inspection Dates: Average Tonnage:					,700				-	
	Average formage				2	,700	ւթս				
	Comments:										
	MSW, transfer										
	Rejected Load	ç.									
•	Date			or Pejection							
		mine		Reason for Rejection							
	2										
	2.										
K. Residential Drop Off: Open During Audit											
ς.			lohei	וש	unng	Auc	111	Х			
	Boxes filling fast, tr	ruck tinning	a of boy								
			y 01 002	103 5	510 W						
						000		aroticas A			
_					L	andi	iii Ohe	erations A		m Page 3 of	

Gas work on North 60 to improve sy	ystem	
* New fiber connections for leachate	and gas system about site	
	Jo-Walter Spear, Jr. Jr. Jr.	
Auditor's Signature:	Brad Van Derkin Digitally signed by Brad Van Derkin Date: 2024.11.22 13:23:19 -06'00'	Date:
Auditor's Printed Name:	Brad Van Derkin Digitally signed by Brad Van Derkin	
		Date:
Management Title		
JSA Principal Signature		Date:





WMWI - Metro Landfill, AUDIT PHOTOS

PROJECT NO. 1036.10056



Working face at South end of Phase 3 for most of the month finishing previous and starting new lift. Shaping slopes and corners



AUDIT PHOTOS - 1



Working face at South end of Phase 3 for most of the month finishing previous and starting new lift. Shaping slopes and corners



Working face at South end of Phase 3 for most of the month finishing previous and starting new lift. Shaping slopes and corners



Working face overlaying from Phase 3 into Phase 2 South end



Working face at South end of Phase 3 for most of the month finishing previous and starting new lift. Shaping slopes and corners



Future cell and covered Southwest corner of Phase 3



Stockpile soil cover being harvested by excavators and dozers



Working face at South end of Phase 3 for most of the month finishing previous and starting new lift. Shaping slopes and corners

WMWI - METRO LANDFILL Action Items Checklist City of Franklin Audit												
Opened:	Opened: Updated: 01/11/2024											
Item Number	DATE	Condition Description	Permit or Contract Reference	Reported to	Initial Schedule for Completion	Actual Completion Date	Elapsed Time (Days)	Notes				
1												