WMWI – PHEASANT RUN LANDFILL

		LANDFIL	L OPERATION TOWN OF P		FORM		
PROJECT	NO. 1115		TOWN OF F	AKIS			
DATE	. =						
DATE		o Atroop		01	TIME	1:35 PM	
	Auditor on sit	e wwpen		Close			
PREVIOUS	S DATE: Februa	ry 5, 2024		Comple	eted \square	East 10to15	mnh
WEATHER	Sunny, clear spring like	e day			WIND		
TEMP A	Maximum 44	°F /	Minimum –	44	°F B.P.	. 29.84	
MAJOR E	EQUIPMENT USED IN LA	NDFILL OP	'ERATIONS				
No.	DESCRIPTION	Rented	Contracted	No.	DESCRIPTION	Rented	Contracted
1	Trailer Tipper						
1	Compactor						
2	Dozer						
1	Excavator						
1	Haul Truck						
	Water Truck						
MAJOR FO	UIPMENT BONEYARD						
No.	DESCRIPTION	Broken	Maintenance	No.	DESCRIPTION	Broken	Maintenance
. Working	Face Size and Location	on:					
Working	g face in Phase 3, nearly in	Phase 4. Re	emoving and cre	ating a ne	w access road		
No othe	r working faces						
					- TO	ENVIRO	VMENTAL
					-0117	2410 N. PALMER ST MILWAUKEE, WI 53	
							315 A345 \$1 GB . Z.C
							Page 1 of 5


	Tarps and auto-fluff							
_								
	<u>-eachate Managemer</u>		_					
_	Discharge to Kenosha							
-	Tanker onsite during audit ~7	75,000 gpc						
-								
(Gas Monitoring and Mo	anagem	ent: Ch	eck approp	oriate box.	_		
	Flares in Operation:	YES	NO 🔳] #				
	Engines in Operation:	YES 🔳] NO [] #	7			
	Shutdowns Since Last A	vudit:	#					
	Destructed Volume:		# 1,900)	cfm			
(Comments:							
-								
-	New cap system connected a				lare last lit la	st week.		
-	New cap system connected a				Flare last lit la	st week.		
-					Flare last lit la	st week.		
	Replacement engine for eng	ine 8 expe	cted 3/7/20				Est. Volume	~0.5"
-	Replacement engine for eng	ine 8 expe	cted 3/7/20	024 Events Since	Last Audit:	# 1		
	Replacement engine for eng	ine 8 expe	cted 3/7/20	024 Events Since	Last Audit:	# 1		
	Replacement engine for eng Surface Water Managem EFFECTS: Note condition of	ine 8 expe	cted 3/7/20	024 Events Since	Last Audit:	# 1		
	Replacement engine for eng Surface Water Managem EFFECTS: Note condition of	nent: of perimetions:	Storm er road, e	024 Events Since rosion contro	: Last Audit: I structures, e	# 1 Prosion dame	age and possible	storm
	Replacement engine for eng Surface Water Managem EFFECTS: Note condition of water/waste contact locati Small snow event last we	nent: of perimetions: ek. Basins	Storm er road, e	Events Since rosion contro	: Last Audit: I structures, e	# 1 Prosion dame	age and possible	storm
	Replacement engine for eng Surface Water Managem EFFECTS: Note condition of water/waste contact locati	nent: of perimetions: ek. Basins	Storm er road, e	Events Since rosion contro	: Last Audit: I structures, e	# 1 Prosion dame	age and possible	storm
	Replacement engine for eng Surface Water Managem EFFECTS: Note condition of water/waste contact locati Small snow event last we	nent: of perimetions: ek. Basins	Storm er road, e	Events Since rosion contro	: Last Audit: I structures, e	# 1 Prosion dame	age and possible	storm
	Replacement engine for eng Surface Water Managem EFFECTS: Note condition of water/waste contact locat Small snow event last we and leachate volumes. Eros	nent: of perimetions: ek. Basins	Storm er road, e	Events Since rosion contro	: Last Audit: I structures, e	# 1 Prosion dame	age and possible	storm
	Replacement engine for enge of the second state of the second state of the second state of the second secon	nent: of perimetions: ek. Basins	Storm er road, e	Events Since rosion contro	: Last Audit: I structures, e	# 1 Prosion dame	age and possible	storm
	Surface Water Managem EFFECTS: Note condition of water/waste contact location of water/waste location	nent: of perimetions: ek. Basins	Storm er road, e	Events Since rosion contro	: Last Audit: I structures, e	# 1 Prosion dame	age and possible	storm
· · · · · · · · · · · · · · · ·	Replacement engine for enge of Surface Water Managemeter Managemeter Managemeter Managemeter Managemeter Master Ma	nent: of perimetions: ek. Basins	Storm er road, e	Events Since rosion contro	: Last Audit: I structures, e	# 1 Prosion dame	age and possible	storm
	Surface Water Managem EFFECTS: Note condition of water/waste contact location of water/waste location	nent: of perimetions: ek. Basins	Storm er road, e	Events Since rosion contro	: Last Audit: I structures, e	# 1 Prosion dame	age and possible	storm
	Replacement engine for enge of Surface Water Managemeter Managemeter Managemeter Managemeter Managemeter Master Ma	nent: of perimetions: ek. Basins	Storm er road, e	Events Since rosion contro	: Last Audit: I structures, e	# 1 Prosion dame	age and possible	storm
- : - : - : - : - : - : - : - : - : - :	Replacement engine for enge of Surface Water Managemeter Managemeter Managemeter Managemeter Managemeter Master Ma	ine 8 expe	Storm er road, e	Events Since rosion contro	: Last Audit: I structures, e	# 1 Prosion dame	age and possible	storm

Litter Control:					
Litter Present Onsite:	YES 🔳	NO []
Litter Present Offsite:	YES	NO [
Laborers Active:		NO [# 2		
Comments:		<u></u>	11		1
Litter heavy on North sig	de of 60th str	eet due to c	able placement	t and tree r	removal
•			·		
Pickers active on North s	side of site				
taken, instances of trucks	on County r	oads.			ss and public roads and control measures very dry. Site roads rutted and a little mu
Inspection of incomin					1
· ·	YES	NO L	#	1	
Equipment Operator:	YES 🔳	NO L	#	3	
Spotter:	YES	NO I	# #		
Random Load Inspection Da	ites:	02/16/			
Average Tonnage:		477 tp	u		
Comments:					
MSW and C&D					
Rejected Loads:					
Date/Time			Re	eason fo	r Rejection
1.					one
2.					
1					
				_	
Residential Drop Off	: Open D	uring Aud	x tib		
White goods awaiting har	ndling, site ve	ery active, b	oxes less than	half full. S	ite clean
		Land	fill Operations A	Audit Form	Page 3 c

Other Comments:	
* Site removing and constructing a new road to the base of Phase 4a	
* Cap project awaiting weather conditions for activities to complete	
Auditor's Signature: Jo-Walter Spear, Jr. Spear, Jr. Date: 2024.02.26 14:24:36 -06'00'	Date:
Management Signature: Michael Buybour Digitally signed by Michael	Date:
Management Filinea Name:	
Management Title: JSA Principal Signature	Date:
50, (1 m.o.p.a. o.g. a.o.o.	

WMWI – Pheasant Run Security Landfill SITE MAP





WMWI PHEASANT RUN LANDFILL / TOWN OF PARIS AUDIT PHOTOS

PROJECT NO. 1155



North screening berm, near corner of 38th Street and HWY 45





Screening berm along 38th Street; plantings appoear to be in bad shape.

Contractor responsable for restoration



Screening berm along 38th Street; plantings appoear to be in bad shape.

Contractor responsable for restoration



Cap project awaiting seeding and minor erosion repairs



Cap project awaiting seeding and minor erosion repairs



Cap project awaiting seeding and minor erosion repairs



Cap project awaiting seeding and minor erosion repairs



Cap project awaiting seeding and minor erosion repairs



Cap project awaiting seeding and minor erosion repairs



Cap project awaiting seeding and minor erosion repairs



Slope erosion on Phase 2 and gas tech actively tweaking well field



Cover roughly placed during operations



Dozer shaping cover, tarp pulled back on covere



Tipper in Phase 4



Phase 3 module 2



Phase 3 & 4 being brought to same elevation



Phase 3 & 4 being brought to same elevation

WMWI Pheasant Run Landfill

Action Items Checklist Town of Paris Audit

Opened:	09/0/2020					Updated:	
Item Number	DATE month/date/year	Condition Description	Permit or Contract Reference	Initial Schedule for Completion	Observed Completion Date	Elapsed Time (Days)	Notes