WMWI – PHEASANT RUN LANDFILL

			LANDFIL	L OPERATION		FORM			
PROJECT	T NO. 1115			TOWN OF P	AKIS				
DATE						TIME	11:15 A	M	
	Audit	tor on site	od;pen		Close				
PREVIOU	IS DATE:	Novem	nber 25, 202	4	Comple	ted [x			
WEATHER Over cast with some s			~				WIND	NW 5 to	
** L/ \	Over cast wi	in some su	11				WINL) N S	S E W
TEMP /	Maximum	30	°F I	Minimum -	30	°F	B.P.	30.2	22
MAJOR E	EQUIPMENT US	ED IN LAI	NDFILL OP	ERATIONS					
No.	DESCRIPTION		Rented	Contracted	No.	DESCRIPT	ION	Rented	Contracted
1	Trailer Ti	pper							
1	Compo	ictor							
1	Doze	er							
	Excavo								
	Haul Truck								
	Water T	ruck							
MAJOR EC	JUIPMENT BONEY	'ARD							
No.	DESCRIPTION		Broken	Maintenance	No.	DESCRIPT	ION	Broken	Maintenance
Working	Face Size and	d Locatio	n:						
Working	face in Northwes	t corner of l	Phase 4, fill	ng in lift. Tipper	relocated	since last au	udit to p	oint into	
- N									
Northwe	st corner								
							2	1	
								ENVIRO	NMENTAL
							7	2410 N. PALMER MILWAUKEE, WI	


Auto-fluff and a plethora of previou	usly tipped soils								
Leachate Management:									
Discharge to Kenosha POTW									
Gas Monitoring and Manager	Gas Monitoring and Management: Check appropriate box.								
Flares in Operation: YES [□ NO ■ #								
Engines in Operation: YES [■ NO								
Shutdowns Since Last Audit:	# None								
Destructed Volume:	# 2,181 cfm								
Comments:									
System operating smoothly since co	System operating smoothly since completion of the cap projects. Gas quality has been high								
Surface Water Management:	Storm Events Since Last Audit: # 1 Est Volume Nil								
_	Storm Events Since Last Audit: # 1 Est. Volume Nil								
_	Storm Events Since Last Audit: # 1 Est. Volume Nil neter road, erosion control structures, erosion damage and possible storm								
EFFECTS: Note condition of perime water/waste contact locations:									
EFFECTS: Note condition of perime water/waste contact locations:	neter road, erosion control structures, erosion damage and possible storm udit. It appears basins are frozen over and there is no flowing water on site								
EFFECTS: Note condition of perime water/waste contact locations: Flurries and spitting rain since last au	neter road, erosion control structures, erosion damage and possible storm udit. It appears basins are frozen over and there is no flowing water on site								
EFFECTS: Note condition of perime water/waste contact locations: Flurries and spitting rain since last au Erosion repaired by cap projects and	neter road, erosion control structures, erosion damage and possible storm udit. It appears basins are frozen over and there is no flowing water on site								
EFFECTS: Note condition of perime water/waste contact locations: Flurries and spitting rain since last au Erosion repaired by cap projects and Odor Control:	udit. It appears basins are frozen over and there is no flowing water on site								
EFFECTS: Note condition of perime water/waste contact locations: Flurries and spitting rain since last au Erosion repaired by cap projects and Odor Control: Odors Present: Onsite	udit. It appears basins are frozen over and there is no flowing water on site								
EFFECTS: Note condition of perime water/waste contact locations: Flurries and spitting rain since last au Erosion repaired by cap projects and Odor Control:	udit. It appears basins are frozen over and there is no flowing water on site								
EFFECTS: Note condition of perime water/waste contact locations: Flurries and spitting rain since last au Erosion repaired by cap projects and Odor Control: Odors Present: Onsite	udit. It appears basins are frozen over and there is no flowing water on site								
Flurries and spitting rain since last au Erosion repaired by cap projects and Odor Control: Odors Present: Comments:	udit. It appears basins are frozen over and there is no flowing water on site It is in good shape. Offsite								
EFFECTS: Note condition of perime water/waste contact locations: Flurries and spitting rain since last au Erosion repaired by cap projects and Odor Control: Odors Present: Comments: No Odors	peter road, erosion control structures, erosion damage and possible storm audit. It appears basins are frozen over and there is no flowing water on site is in good shape. Offsite								

_								
G.	Litter Control:		l	7		1		
	Litter Present Onsite:	YES 🔳						
	Litter Present Offsite:	YES _	NO 📗					
	Laborers Active:	YES 📕	NO L	#				
	Comments:							
	Litter in good shape con	sidering Dec	ember win	ds, litter mostly	about worl	king face		
	Fences well aligned for o	atching litter						
Н.	Vehicle Impacts: Locations of excessive mud/dust, condition of access and public roads and control measures taken, instances of trucks on County roads. Area roads clean and clear. Site access and scale improved.							
	Site roads hard and clea	r, not dusty						
		·						
١.	Inspection of incoming	g Waste:						
	Scale Camera Operator:	YES	NO 🗌	#	1			
	Equipment Operator:	YES 🔳	NO 🗌	#	3			
	Spotter:	YES	NO 🔳	#				
	Random Load Inspection Da	12/03/2	2024					
Average Tonnage:			788.54	tpd				
	Comments:							
	MSW, soil proje	∍ct						
J.	Rejected Loads:					,		
	Date/Time			Re	eason fo	r Rejection		
	1.							
	2. None							
K.	Residential Drop Off:	Open D	uring Au	dit x]			
	Povos mostly open but om	nty eito oloo	n Active :	icor during audit	ened thru	operation		
	Boxes mostly open, but empty, site clean. Active user during audit sped thru operation							
			Lanc	Ifill Operations A	uudit Form	Page 3 of 5		
			LUITC	iiii Operalions A	wan roill	1 uge 3 01 3		

Other Comments:	
* One operator acting as mechanic for the day	
* Roadways being redressed with asphalt millings to improve surface and ridability	
Auditor's Signature: Jo-Walter Spear, Jr. Spear, Jr. Spear, Jr. Digitally signed by Jo-Walter Spear, Jr. Date: 2024.12.06 12:20:07 -06'00'	Date:
Management Signature: Michael Puybaum Burbara	Date:
Management Title:	
JSA Principal Signature	Date:


WMWI – Pheasant Run Security Landfill SITE MAP





WMWI PHEASANT RUN LANDFILL / TOWN OF PARIS AUDIT PHOTOS

PROJECT NO. 1155



Dozer spreading tailings to smooth access roads





West slope of cap project, vegetation is developing quickly



West slope of cap project, vegetation is developing quickly



West slope of cap project, vegetation is developing quickly



Transition of cap to capless of Phase 3



Cap project greening rapidly



Northwest corner of Phase 3, slow to green



Plethora of soils tipped in Phase 4 for cover



Truck tipping into working face in Northwest corner of Phase 4



Tipper with stockpiling of cover on East side



Active area in Phase 4



Tipper aimed into Northwest corner of Phase 4



Tipper carrier placed adjacent to gas well to protect it

WMWI Pheasant Run Landfill

Action Items Checklist Town of Paris Audit

Updated: Opened: 09/0/2020 Initial Permit or Observed Elapsed Schedule DATE month/date/year Completion Time **Condition Description** Contract Notes **Item Number** for Reference Date (Days) Completion