
	E June 20, 2024 Auditor on site at:	Open		Close		IL 112.0	05 PM	
PREVIOUS DATE: May 28,2024				_Completed X				
NEATHE	R Overcast, previous rai	n some clear	ing of clouds du	North 5 to 10 Is during audit WIND N S				
	, p						S E W	
TEMP	Maximum 84	4 °F	Minimum	64	°F B.	P. 30.55		
NO.	EQUIPMENT USED IN LA DESCRIPTION	Rented	Contracted	No.	DESCRIPTION	Rented	Contracted	
1	Trailer Tipper	Kenteu	Contracted	NO.	DESCRIPTION	Rented	Contracted	
2	Compactor							
1	Dozer							
1	Excavator							
1	Haul Truck							
	Water Truck							
	QUIPMENT BONEYARD							
No.	DESCRIPTION	Broken	Maintenance	No.	DESCRIPTION	Broken	Maintenand	
Markina	· Face Cize and Least							
/vorking	Face Size and Locati	OH.						
Norkina f	ace in new cell at North end	d bringing lift	Southward over	fluff laver o	f new cell			
, i oritarig i								


Page 1 of 6

	Cover Material:								
	Soils and MRF Fines								
· ·									
· ·									
В.	Leachate Management:								
	Discharge to MMSD ×								
'	Discharge Volume: 50,000 gpd								
	Leachate Head Levels: Within statutes								
C.	Gas Monitoring and Management: Check appropriate box.								
	Flares in Operation: YES 🔲 NO 🗌 # 1								
	Turbines in Operation: YES 🔲 NO 🗌 # 1								
	Engines in Operation: YES 🔲 NO 🗌 # 3								
	Shutdowns Since Last Audit: # None								
	Destructed Volume: # 3,200 cfm								
	Comments:								
	One engine offline for replacement. No shutdowns, Pheasant Run staff operating system								
D.	Surface Water Management:Storm Events Since Last Audit:# 2Est. Volume< 1"								
	EFFECTS: Note condition of perimeter road, erosion control structures, erosion damage and possible storm water/waste contact locations:								
	Basins have free board. No changes to erosion.								
E.	Odor Control:								
	Odors Present: Onsite Offsite Notes on odor monitoring page								
	Comments:								
	No odors								
F.	Liquid Loads Received:								
	10% of MSW tipping or less								
	Page 2 of 6								

Litter Control:	V/F0				7	
Litter Present Onsite					-	
Litter Present Offsite					-	
Laborers Active:	YES		# 2			
Comments:						
Litter being collected fro	om Northeast co	orner				
Vehicle Impacts: L taken, instances of true US 45 gritty with some	cks on County	roads.			ess and public roads and control measur conditions	res
Inspection of incor						
Scale Camera Operation			#	1	-	
Equipment Operator:	YES		#	6	-	
Spotter:	YES		#		-	
Random Load Inspecti	on Dates:	06/20/20	4			
Average Tonnage:		2,400 tp	d			
Comments:						
MSW, C&D						
Rejected Loads:						
Date/Tim	e			leason fo	or Rejection	
1.						
2.						
Residential Drop (on: jupen L	During Audi	IT 🗌			
Site closed, clean and b	oxes being em	ρτιeα				
		Landfil	l Operations	Audit Form	Page 3	3 of
		Landii			i age c	5 01

No additional activities		
	Digitally signed by Jo-Walter Spear,	
Auditor's Signature	Jo-Walter Spear, Jr. Date: 2024.06.20 12:23:01 -05'00' Brad Van Derkin Date: 2024.06.20 12:23:01 -05'00'	Date:
Auditor's Printed Name:		Date.
Management Signature:	Brad Van DerKin Date: 2024.06.20 12:25:01 -05'00'	Date:
Management Printed Name:		
Management Title:		
JSA Principal Signature		Date:





WMWI - Metro Landfill, AUDIT PHOTOS

PROJECT NO. 1036.10056



Overview of active area



AUDIT PHOTOS - 1

JSA ENVIRONMENTAL



Transition from Phase 1 thru 3



Phase 1 & 2 receiving additional intermediate cover



Phase 1 with fresh intermediate cover



Working face in near middle of Phase 3, moving Southward



Working face width of whole cell and 1/4 of the length. No cover stockpiles

WMWI - METRO LANDFILL Action Items Checklist City of Franklin Audit										
Opened:	Opened: Updated: 01/11/2024									
Item Number	DATE	Condition Description	Permit or Contract Reference	Reported to	Initial Schedule for Completion	Actual Completion Date	Elapsed Time (Days)	Notes		
1										
	I	1		1	I	1		11		