

DATE	July 18, 2024 Auditor on site at:	Open		Close		ИЕ <u>3:2</u>	25 PM
PREVIOU	IS DATE:	June 27, 2024	1	Comple	ted 🗵		
				_ '		S 0 to 5	-
WEATHER	Cloudy and Sun				WIN	ND N	S E W
TEMP	Maximum 76	°F	Minimum _	56	°F B	.P. 30.20	
	equipment used in La						
No.		Rented	Contracted	No.	DESCRIPTION	Rented	Contracted
1	Trailer Tipper	Rontou	Contractor		DECOMINION	Rontou	
2	Compactor						
2	Dozer						
1	Excavator						
1	Haul Truck						
	Water Truck						
MAJOR EC	L QUIPMENT BONEYARD						
No.	DESCRIPTION	Broken	Maintenance	No.	DESCRIPTION	Broken	Maintenanc
1	Dozer		Rebuild				
1	Compactor		Rebuild				
Working	Face Size and Locati	on:					
North end	of Phase 3 nearly 3/4 acro	ss phase and	l end of current l	lift			
North end	of Phase 3 nearly 3/4 acro	ss phase and	l end of current l	lift			

	Cover Material:							
	Comingled seconds and excavated soil							
B.	Leachate Management: Discharge to MMSD]						
	Discharge Volume: Leachate Head Levels: All w	ith in stat	utes					
C.	Gas Monitoring and Managem		1	ate box.	7			
	Flares in Operation: YES		#	1	_			
	Turbines in Operation: YES		#	1	_			
	Engines in Operation: YES] NO 🗌	#	3				
	Shutdowns Since Last Audit:	# Jul	y 15					
	Destructed Volume:	#		cfm				
	Comments:							
	Power outage on the late hours of J	uly 14, 2024	shutdown pla	nt, back on	line prior to	site opening no other	issues	
	Surface Water Management:	Storm Ev	vents Since La	act Audit:	# 501	Ect Volumo	3+"	
D.	-					Est. Volume		
	EFFECTS: Note condition of perimeter water/waste contact locations:	er road, erc	osion control st	ructures, e	rosion dam	hage and possible sto	orm	
	Basins have freeboard, erosion unchan	nged. Signifi	icant area flood	ling				
E.	Odor Control: Odors Present: Onsite		Offsite		Notes or	n odor monitoring	page	
	Comments:							
	Strong organic oc	dor						
F.	Liquid Loads Received:							
	Typical loading							
							Page 2 d	of 6

Litter Control:					7
Litter Present Onsite:	YES 🔳	NO 🗌			
Litter Present Offsite:	YES 🗌	NO 🔳			
Laborers Active:	YES 🔳	NO 🗌	# 3		
Comments:					
Laborers picking litter an	d weed eattin	ng			
 Vehicle Impacts: Loca taken, instances of trucks 			dust, conditio	n of acce	ess and public roads and control measures
			a de alterna de directo	t da har	
US 45 clean and dry, no	debris act	ive sweepe	r during audit, b	out dry bru	sh
Site roads clean and dus	t froo				
Inspection of incomin	a Masta:				
Inspection of incoming Scale Camera Operator:	YES	NO 🗌	#	1	1
Equipment Operator:	=			7	-
Spotter:	YES		#		-
	YES	NO 🔳	#		-
Random Load Inspection	Jales:	2.50	O tool month o		-
Average Tonnage:		2,50	0 tpd - month a	ver	
Commonto					
Comments: MSW, soils, C&D, and					
Rejected Loads:					
Date/Time			Re	ason fo	r Rejection
1			NC		one
2.					
Ζ.					
Residential Drop Off:	Open D	uring Aud	it 🗌	1	
				1	
Site clean, yard waste volu	me growina.	site prepare	d for tomorrow		
		1 .1			
		Landfi	III Operations A	udit Form	Page 3 of 6
			•		5

	ste mass	
Walsh backhaul active repairing ha	ul roads after rain events, no hauling	
	, ,	
	Jo-Walter Spear, Jr. Digitally signed by Jo-Walter Spear, Jr. Date: 2024.07.18 16:43:39 -04'00'	5
	Date: 2024.07.18 16:43:39 -04 00	Date:
Auditor's Signature		Date: 7/18/24
Auditor's Printed Name		
Auditor's Printed Name Management Signature	Michaela Tiefengraber	
Auditor's Printed Name Management Signature Management Printed Name	Michaela Tiefengraber	
Auditor's Printed Name Management Signature Management Printed Name Management Title	Michaela Tiefengraber DOMT	
Auditor's Printed Name Management Signature Management Printed Name Management Title	Michaela Tiefengraber	
Auditor's Printed Name Management Signature Management Printed Name Management Title	Michaela Tiefengraber DOMT	Date:





WMWI - Metro Landfill, AUDIT PHOTOS

PROJECT NO. 1036.10056



Phase 3, half of phase as working face, cover prepared about waste



AUDIT PHOTOS - 1



Overview of North Expansion West, Phase 3



West slope and body of Phase 2

JSA ENVIRONMENTAL



Top of Phase 1 &2



Northeast corner of Phase 1

WMWI - METRO LANDFILL Action Items Checklist City of Franklin Audit											
Opened:	Opened: Updated: 01/11/2024										
Item Number	DATE	Condition Description	Permit or Contract Reference	Reported to	Initial Schedule for Completion	Actual Completion Date	Elapsed Time (Days)	Notes			
1											
	I	1		1	I	1		11			