27 (11	EAuditor	July 29, 2024 on site @p	l en		Close		TIME	9:04 AN	1
	JS DATE:	July 11, 20			Comple	eted X			_
VEATHER	र Light rain, some	e sun					WIND	E 0 to	
	Maximum  EQUIPMENT USED	82		Minimum - ERATIONS	82			30.1	
40.	DESCRIPTION		nted	Contracted	No.	DESCRIPTIO	N	Rented	Contracte
1	Trailer Tipp	er							
1	Compacto	or							
1	Dozer								
	Excavato	r							
	Haul Truc	k							
	Water Truc	ck							
MAJOR EC	_  Quipment boneyar	<u> </u>   D							
٧٥.	DESCRIPTION	Bro	ken	Maintenance	No.	DESCRIPTIO	NC	Broken	Maintenar
Norking	Face Size and L	ocation:							

ENVIRONMENTAL

2410 N. PALMER STREET
MILWAUKEE, WI 53212-3606

Page 1 of 5


	Cover Material:		
_	Auto-Fluff		
L	eachate Management:		
	ischarge to Kenosha POTW		
_	No tankers evident during audit		
	Gas Monitoring and Manageme	ent: Check appropriate box.	
F	ares in Operation: YES 🗌	NO <b> </b> # 0	
E	ngines in Operation: YES 🔳	NO  # 8	
S	hutdowns Since Last Audit:	# None	
	estructed Volume:	# 2,286 cfm	
C	omments:		
_	Mowers hit same ass wells or nines or	n new cap, causing areas to be shut off, but no shutdowns	
_	Willowers the sollie gas wells of pipes of	Thew cap, causing areas to be shut on, but no shutdowns	
_			
_	urface Water Management	Storm Events Since Last Audit: # 2 Fet Value	0 4"
	urface Water Management:	Storm Events Since Last Audit: # 3 Est. Volum	
Е		Storm Events Since Last Audit: # 3 Est. Volumer road, erosion control structures, erosion damage and possible	
Е	FFECTS: Note condition of perimeter ater/waste contact locations:	!	
Е	FFECTS: Note condition of perimeter ater/waste contact locations:	er road, erosion control structures, erosion damage and possibl	
E w	FFECTS: Note condition of perimeter atter/waste contact locations:  Rain dropped off thru mid July. Site of the Area flooding all receded	er road, erosion control structures, erosion damage and possibl	
E w	FFECTS: Note condition of perimeter ater/waste contact locations:  Rain dropped off thru mid July. Site of the Area flooding all receded.  Odor Control:	er road, erosion control structures, erosion damage and possible erosion minimal and basins have plenty of freeboard.	
E w	FFECTS: Note condition of perimeter atter/waste contact locations:  Rain dropped off thru mid July. Site of the Area flooding all receded  Odor Control: Odors Present:  Onsite	er road, erosion control structures, erosion damage and possibl	
E w	FFECTS: Note condition of perimeter ater/waste contact locations:  Rain dropped off thru mid July. Site of the Area flooding all receded.  Odor Control:	er road, erosion control structures, erosion damage and possible erosion minimal and basins have plenty of freeboard.	
E w	FFECTS: Note condition of perimeter atter/waste contact locations:  Rain dropped off thru mid July. Site of the Area flooding all receded  Odor Control: Odors Present:  Onsite	er road, erosion control structures, erosion damage and possible erosion minimal and basins have plenty of freeboard.	
	FFECTS: Note condition of perimeter atter/waste contact locations:  Rain dropped off thru mid July. Site of the Area flooding all receded  Odor Control: Odors Present: Comments:	er road, erosion control structures, erosion damage and possible erosion minimal and basins have plenty of freeboard.	
	FFECTS: Note condition of perimeter atter/waste contact locations:  Rain dropped off thru mid July. Site of the Area flooding all receded  Odor Control: Odors Present: Comments:  No odors	er road, erosion control structures, erosion damage and possible erosion minimal and basins have plenty of freeboard.  Offsite	

G.	Litter Control:			-1		1
	Litter Present Onsite:	YES	NO 🔳			
	Litter Present Offsite:	YES	NO L			
	Laborers Active:	YES 🔳	NO [	]# 2		
	Comments:					
	Laborer's picking local ro	ads while ra	in is light.	Laborer's mov	ving later in	day
Н.	Vehicle Impacts: Locat	tions of exce	essive mud	d/dust, conditi	on of acce	ss and public roads and control measures
	taken, instances of trucks o	n County ro	oads.			
	US 45 and area roads cl	ean and wit	hout dust.	Scale access	improved w	with placement of fine stone to fill potholes
	site roads hard, smooth w	ith little dust	t			
l.	Inspection of incoming	g Waste:				_
	Scale Camera Operator:	YES	NO 🗌	#		
	Equipment Operator:	YES 🔳	NO $\square$	#	3	
	Spotter:	YES	NO 🔳	#		
	Random Load Inspection Date	es:	7/2	6/2024		
	Average Tonnage:		6′	14 tpd		
	Comments:					
	MSW, C&D					
J.	Rejected Loads:					
	Date/Time			F	Reason fo	r Rejection
	1.					
	2.				NC	DNE
					_	
K.	Residential Drop Off:	Open Du	uring Au	dit 🗵		
	Very active during audit,	site clean ar	nd boxes m	nostly empty		
			Lanc	Ifill Operations	Audit Form	Page 3 of 5

Other Comments:	
* Site operator mowing existing cap grasses	
* Contractor making gas system improvements in the field with piping improvements	
* Contractor repairing sideslope riser pump	
Auditor's Signature: Jo-Walter Spear, Jr. Spear, Jr. Spear, Jr. Date: 2024.07.29 09:40:45 -05'00'	Date:
Management Signature: Michael Buxbaum Rycham Rycham	Date:
Management Title:	
JSA Principal Signature	Date:

## WMWI – Pheasant Run Security Landfill SITE MAP





## WMWI – Pheasant Run Landfill LANDFILL CONSTRUCTION AUDIT FORM Town of Paris PROJECT NO. 1115

MA IOP	EQUIPMENT USED IN C	CONICTOLIC		SIAOI			
10.	DESCRIPTION	Rented	Contracted	No.	DESCRIPTION	Rented	Contracte
	Scrapper						
2	Dozer						
1	Excavator						
3	Haul Truck						
	Water Truck						
	Sweeper						
Con	adder placing parties cental	ind rooting zoi	ne layer on both	i sides of I	Priase 2 Cap		
Con	autor pluonig burner com u	ind rooting 20	ne layer on both	a sides of I	-паѕе 2 Сар		
Con		ind rooting 20	ne layer on both	a sides of I	глаѕе 2 Сар		
Con		ind rooting 20	ne layer on both	a sides of I	Priase 2 Cap		
Con		Ind rooting 20	ne layer on both	a sides of I	Friase 2 Cap		
Con		Ind rooting 20	ne layer on both	a sides of I	Friase 2 Cap		

Landfill Operations Audit Form

Page 1 of 2

All soils being excavated on site	
Off Site Hauling	
Weight Ticket Number	Weight of Load in Pounds
1	
3	
4	
5	
6	
7	
8 9	
10	
10	
Auditor's Signatura	Digitally signed by Jo-Walter Doto
Auditor's Signature:  Auditor's Printed Name:  Management Signature:	Digitally signed by Jo-Walter Spear, Jr. Date: 2024 07 29 09:43:19 -05'00'
Management Signature: Nation of Development	Digitally signed by Michael Date:
Management Signature:  Michael Buxbaum  Management Title:	Date: 2024.07.29 09:45:28 -05'00'
Management Title:	

Landfill Operations Audit Form

Page 2 of 2